THP2
THERMO-HYGROMETER PEN

SPECIFICATIONS

Temp. Measurement Range	-4°F to +122°F (-20°C to +50°C)
Temp. Measurement Accuracy	+/-2°F / +/-1°C
Temp. Display Resolution	0.1 degree
Relative Humidity Measurement Range	10% to 90% RH
Relative Humidity Measurement Accuracy	+/-5% for range of 40% to 80% RH, otherwise +/-7%
Relative Humidity Display Resolution	1% RH
Ambient Operating Temp. Range	-4°F to +122°F (-20°C to +50°C)
Ambient Operating Humidity Range	10% to 95% RH

INSTRUCTIONS

On/Off Button
Turns the unit on and off.

Max/Min Button
Press to turn the unit to the maximum record mode, where the maximum measured values of temperature and humidity are shown. An upward pointing arrow indicates the unit is in the maximum record mode.

Press again, and the unit will show the minimum record of temperature and humidity measured. A downward pointing arrow indicates this mode. Press button again to return to the normal mode.

Clear Button
Press to clear the maximum and minimum records, as indicated by a show of three bars. New records will be displayed in three seconds.

C/F Button
Press this button to switch between °F/°C temperature units.

This product is powered by a button type 1.5 V battery (p/n STBAT). Change battery when display looks dim. Battery life is dependent on frequency of use. Avoid exposure to direct sun light or harsh and contaminated environment.

Made in China

Supco

SEALED UNIT PARTS CO., INC.
P.O. Box 21, 2230 Landmark Place
Allenwood, NJ 08720
www.supco.com

6 87152 14832 5